


To: Patrick Hamlin, USEPA

From: Wendy Vorwerk, DERR-SIFU thru Christine Osborne, SIFU Supervisor

Date: December 10, 2015

Subject: Mullins Rubber SI Dry Well Sample Clarification

As part of the Mullins Rubber SI conducted in November 2010, a water sample (GW-8) was collected from the dry well that received non-contact cooling water from the TCE tanks. The text portion of the SI report is correct. However, the sample location of GW-8 depicted on the Sample Location Map (Figure 4 in the SI) is in error. The Sample Location Map shows that GW-8 was collected from dry well #1. The sample was actually collected from dry well #2. Below is a portion of the site schematic map (included in the SI as Figure 3) that correctly depicts the location of GW-8.



If you have any questions, please contact me at 614-836-8759.

Thank you,

A handwritten signature in cursive script, appearing to read "Wendy Vorwerk".

**Wendy Vorwerk**

**Ohio EPA | Division of Environmental Response and Revitalization**

Site Investigation Field Unit

4675 Homer-Ohio Lane, Groveport, OH 43125

Ph: 614-836-8759

Fax: 614-836-8795

[wendy.vorwerk@epa.ohio.gov](mailto:wendy.vorwerk@epa.ohio.gov)